

BL-1718

Turning discs on the vehicle is the recommended method of using the device, as it provides significantly better results due to proper centering of the disc. It greatly reduces the risk of the disc becoming unbalanced after the repair.



Dane techniczne

Disc thickness	39 mm
Indication accuracy	≤ 0.002 - 0.005 mm
Feed	8.5 mm/min.
Measuring speed	98 obr./min.







